



VEHICLE INSPECTION REPORT

BA19WOB

Nissan Leaf 110kW Tekna 40kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/06/2019	Keys	2	CAP Clean	£6,975.00
Year	2019	Service history	Yes	CAP Average	£6,500.00
Mileage	25,932 Miles Warranted	Service documents	Printout	CAP Below	£6,025.00
Fuel Type	Electric	Number of stamps	4	Gearbox	AUTOMATIC
Colour	RED	Last service date	18/05/2023	Gears	1
VIN	SJNFAAZE1U0063362	Last service miles	15,338	Doors	5
Body Style	Hatchback	MOT Due	17/05/2026		

£100 ADDITIONAL FEE

Last Service -18.05.2023 at 15338 miles (4 main dealer services) One charging cable

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Partial leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5



4: Door nsf
Chipped
Edge Chip



5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint




8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Poor Previous Repair
Poor Paint



10: Door osr
Scratched
Over 25mm Thru Paint



11: Door osf
Scratched
UpTo 25mm Thru Paint



12: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



13: Wing osf
Chipped
1 To 5



14: Roof
Chipped
1 To 5

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK