



# VEHICLE INSPECTION REPORT

**GY71JWO**

## MG Mg 5 EXCLUSIVE

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
**5**

### Details

Reg. date 18/10/2021

Year 2021

Mileage 62,766 Miles Not Warranted

Fuel Type Electric

Colour BLACK

VIN LSJE24094LG097395

Body Style Estate

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 3

Last service date 17/10/2024

Last service miles 49,417

MOT Due 17/10/2025

CAP Clean £7,700.00

CAP Average £6,775.00

CAP Below £5,850.00

Gearbox AUTOMATIC

Gears 1

£100 ADDITIONAL FEE

Last Service - 17.10.2024 at 49417 miles (3 main dealer services)

No charging cables

### Tyres

NSF TRIANGLE 3.0mm

NSR BRIDGESTONE 5.0mm

OSF TRIANGLE 3.0mm

OSR BRIDGESTONE 5.0mm

Spare

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Bumper Front Moulding  
Scuffed (Unpainted)  
Over 100mm



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsf  
Scratched  
Over 25mm Thru Paint



7: Door nsr  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
Between 10mm + 30mm






9: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



10: Qtr Panel osr  
Dented  
With Paint Damage



11: Door osr  
Dented  
With Paint Damage



12: Door osf  
Dented  
Over 30mm



13: Wheel osf  
Scratched  
Over 50mm



14: Wing osf  
Scratched  
Over 25mm Thru Paint



15: Roof  
Chipped  
Edge Chip

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK