



VEHICLE INSPECTION REPORT

LN64DXR

Ford S-Max 2.2 TDCi 200 Titanium X Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/09/2014	Keys	2	CAP Clean	£3,150.00
Year	2014	Service history	Yes	CAP Average	£2,600.00
Mileage	139,755 Miles Warranted	Service documents	Electronic / Online	CAP Below	£2,100.00
Fuel Type	Diesel	Number of stamps	2	Gearbox	MANUAL
Colour	WHITE	Last service date	06/02/2025	Gears	6
VIN	WF0SXXGBWSEP82358	Last service miles	133,587		
Body Style	MPV	MOT Due	25/10/2025		

£65 ADDITIONAL FEE.

Last Service - 06.2.2025 at 133587 miles (2 confirmed services at Visick Cars)

Exhaust leak, horn not working

Tyres


NSF	LAUFENN	2.0mm
NSR	BUDGET	5.0mm
OSF	LAUFENN	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Insecure
Action Required



3: Bumper Front
Cracked
Over 25mm



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Over 50mm



6: Sill Panel Trim ns
Broken
Replace



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Cracked
Over 25mm



12: Lamp nsr
Broken
Replace



13: Tailgate
Dented
Between 10mm + 30mm



14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
Between 10mm + 30mm



17: Door osf
Chipped
Edge Chip



18: Screen Front
Cracked
Replace



19: Wing osf
Chipped
Multiple Chips



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK