



VEHICLE INSPECTION REPORT

GU70ULK

Audi A5 40 TFSI Edition 1 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	07/09/2020	Keys	2	CAP Clean	£17,900.00
Year	2020	Service history	Yes	CAP Average	£16,700.00
Mileage	76,516 Miles Warranted	Service documents	Printout	CAP Below	£15,500.00
Fuel Type	Petrol	Number of stamps	1	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	06/09/2024	Gears	7
VIN	WAUZZZF58LA017192	Last service miles	57,434	Doors	5
Body Style	Hatchback	MOT Due	06/09/2025		

£65 ADDITIONAL FEE

Last service 06/09/2024 at 57,434 miles- 1 service

Tyres


NSF	UNIROYAL	3.0mm
NSR	UNIROYAL	4.0mm
OSF	UNIROYAL	4.0mm
OSR	UNIROYAL	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Audio remote control
- Air conditioning
- Front armrest
- Rear armrest
- ABS
- Side airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Climate control
- Front electric windows
- Rear electric windows
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Rear headrests
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint




3: Boot Lid
Chipped
1 To 5

4: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Dented
With Paint Damage

6: Wheel nsr
Scratched
Over 50mm




7: Door nsr
Chipped
1 To 5

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Dented
Over 2 UpTo 10mm



10: Door nsf
Scratched
Over 25mm Not Thru Paint



11: Wing nsf
Chipped
1 To 5



12: Wing nsf
Scratched
Over 25mm Not Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bonnet
Chipped
Multiple Chips



15: Bumper Front
Chipped
Multiple Chips

No Image


16: Bumper Front
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Up To 50mm

No Image

18: Wing osf
Scratched
Over 25mm Not Thru Paint



19: Screen Front
Chipped
UpTo 10mm



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Door osr
Poor Previous Repair
Poor Paint



23: Qtr Panel osr
Chipped
Multiple Chips



24: Wheel osr
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK