



VEHICLE INSPECTION REPORT

HV62GCU

Hyundai I20 1.2 Style 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	N/A



Details

Reg. date	21/09/2012	VIN	MALBB51BLDM446094	CAP Average	£910.00
Year	2012	Body Style	Hatchback	CAP Below	£500.00
Mileage	112,160 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	30/05/2025	Gears	5
Colour	BLACK	CAP Clean	£1,300.00	Doors	5

£100 ADDITIONAL FEE. Elm on and tapping engine.

Noise while pulling away

Boot struts weak

Tyres

NSF	BUDGET	Worn
NSR	ROADSTONE	4.0mm
OSF	ROADSTONE	4.0mm
OSR	BUDGET	Worn
Spare		

Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- Solid Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Steering wheel rake adjustment
- Drivers airbag
- Central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Isofix child seat anchor points
- Remote central locking

Photos






Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Poor Previous Repair
Poor Paint



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wing osf
Scratched
Over 25mm Thru Paint



5: Wheel osf
Scratched
Over 50mm



6: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



7: Door osf
Dented
Between 10mm + 30mm



8: Door osr
Poor Previous Repair
Poor Paint



9: Qtr Panel osr
Dented
With Paint Damage



10: Wheel osr
Scratched
Over 50mm



11: Bumper Rear
Hole
Over 25mm



12: Boot Lid
Rusted
Over 5mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Door nsr
Dented
With Paint Damage



15: Wheel nsf
Scratched
Over 50mm



16: Door nsf
Chipped
Multiple Chips




17: Door Mirror Assy nsf
Broken
Replace



18: Wing nsf
Scratched
Over 25mm Thru Paint



19: Wheel nsf
Scratched
Over 50mm



20: Tyre nsf
Worn
Replace

No Image



21: Tyre osr
Worn
Replace

22: Handle Inner nsf
Damaged
Replace

No Image

No Image

23: Tyre nsf
Worn
Replace

24: Tyre osr
Worn
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Poor
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK