



VEHICLE INSPECTION REPORT

GY21LMO

Jeep Renegade 1.0 T3 GSE Night Eagle II 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	28/05/2021	Keys	1	CAP Clean	£10,900.00
Year	2021	Service history	Yes	CAP Average	£9,750.00
Mileage	45,046 Miles Warranted	Service documents	Printout	CAP Below	£8,575.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	29/07/2025	Gears	6
VIN	1C4NJCE31MPM26509	Last service miles	45,018		
Body Style	Estate	MOT Due	27/01/2026		

£100 ADDITIONAL FEE.

Last service 29/07/2025 at 45,018 miles- 2 main dealer services Lacking power/ Stutter on pull away





Tyres		
NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

No Image

3: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Up To 50mm

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Chipped
1 To 5

No Image

7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Door nsf
Chipped
1 To 5

No Image



9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Wing nsf
Chipped
1 To 5



11: Bumper Front
Chipped
Multiple Chips

No Image

12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Bonnet
Chipped
1 To 5




14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Up To 50mm



16: Door osf
Dented
2 Or Less UpTo 10mm



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Qtr Panel osr
Dented
With Paint Damage

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK