



VEHICLE INSPECTION REPORT

DT17UCH

Nissan Qashqai 1.5 dCi Tekna 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/06/2017	Keys	2	CAP Clean	£4,750.00
Year	2017	Service history	Yes	CAP Average	£4,100.00
Mileage	96,061 Miles Warranted	Service documents	Service Book	CAP Below	£3,450.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	BLACK	Last service date	10/01/2025	Gears	6
VIN	SJNFAAJ11UZ085289	Last service miles	82,753	Doors	5
Body Style	Hatchback	MOT Due	11/01/2026		

£100 ADDITIONAL FEE

Last service 10/01/2025 at 82,753 miles- 8 services Slight rattle at idle

Tyres



NSF	BUDGET	3.0mm
NSR	MAXXIS	3.0mm
OSF	BUDGET	Worn
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake




3: Other
N/A
N/A



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5




6: Wing nsf
Scratched
Over 25mm Not Thru Paint




7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Scratched
UpTo 25mm Thru Paint




10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



14: Bumper Rear
Chipped
Multiple Chips

No Image

15: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image


16: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Over 50mm




19: Door osr
Dented
Over 2 UpTo 10mm



20: Door osf
Dented
Between 10mm + 30mm



21: Wing osf
Chipped
1 To 5



22: Wing osf
Scratched
Over 25mm Not Thru Paint



23: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		