



VEHICLE INSPECTION REPORT

GU110OF

Honda Jazz 1.4 i-VTEC ES-T 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	05/03/2011	Keys	2	CAP Clean	£1,125.00
Year	2011	Service history	Yes	CAP Average	£740.00
Mileage	145,393 Miles Warranted	Service documents	Service Book	CAP Below	£350.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	SILVER	Last service date	20/11/2018	Gears	5
VIN	SHHGG6760CU002413	Last service miles	71,461	Doors	5
Body Style	Hatchback	MOT Due	28/11/2025		

Clutch replaced 07/08/2025.

Last service 20/11/2018 at 71461 miles (6 services (4 main dealer)).

Tyres



NSF	NEXEN	4.0mm
NSR	GENERAL TIRE	3.0mm
OSF	NEXEN	4.0mm
OSR	GENERAL TIRE	3.0mm
Spare		

Features


- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Back Cover osf
Torn
Over 3mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Poor Previous Repair
Poor Paint



9: Door nsr
Chipped
Multiple Chips



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Poor Previous Repair
Poor Paint



13: Boot Lid
Poor Previous Repair
Poor Paint



14: Qtr Panel osr
Dented
Over 30% Of Panel



15: Roof
Dented
Over 30mm



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Dented
With Paint Damage



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: A Post os
Chipped
1 To 5



21: Wing osf
Dented
With Paint Damage



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK