



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

BG62UTY

Mini Countryman 2.0 Cooper S D ALL4 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/11/2012	Body Style	Hatchback	CAP Below	£2,575.00
Year	2012	Keys	2	Gearbox	AUTOMATIC
Mileage	78,016 Miles Warranted	Service history	None	Gears	6
Fuel Type	Diesel	MOT Due	03/10/2025	Doors	5
Colour	BLUE	CAP Clean	£3,575.00		
VIN	WMWZD72080WN31037	CAP Average	£3,075.00		

NO Service History Vibration/rattle at idle

Tyres


NSF	NANKANG	4.0mm
NSR	NANKANG	5.0mm
OSF	NANKANG	4.0mm
OSR	NANKANG	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Radio/CD
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Trip computer
- Electric door mirrors
- Climate control
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Rear parking sensor
- Audio remote control
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Dented
Between 10mm + 30mm



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Dented
With Paint Damage



8: Bumper Rear
Poor Previous Repair
Poor Paint

No Image



9: Boot Lid
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Over 50mm



12: Door nsr
Dented
With Paint Damage



13: Door nsf
Chipped
1 To 5



14: Wheel nsf
Scratched
Over 50mm



15: Seat Base Cover osf
Torn
Over 3mm

16: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK