



# VEHICLE INSPECTION REPORT

**LN14HFA**

## Nissan Qashqai 1.2 DiG-T Acenta Premium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/03/2014	Keys	2	CAP Clean	£3,100.00
Year	2014	Service history	Yes	CAP Average	£2,600.00
Mileage	80,956 Miles Warranted	Service documents	Service Book	CAP Below	£2,075.00
Fuel Type	Petrol	Number of stamps	11	Gearbox	MANUAL
Colour	SILVER	Last service date	19/09/2024	Gears	6
VIN	SJNFEAJ11U1072294	Last service miles	66,299	Doors	5
Body Style	Hatchback	MOT Due	25/07/2026		

Last service 19/09/2024 at 66,299 miles- 11 services (6 main dealer) Eml light is on, high clutch

### Tyres

NSF	BUDGET	6.0mm
NSR	RAPID	5.0mm
OSF	BUDGET	6.0mm
OSR	RAPID	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Wing nsf  
Scratched  
Over 25mm Thru Paint



4: Wheel osf  
Scratched  
Over 50mm



5: Door nsf  
Poor Previous Repair  
Paint Flake



6: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door nsr  
Scratched  
Over 25mm Thru Paint



8: Wheel nsr  
Scratched  
Over 50mm





9: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Tailgate  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Over 50mm



13: Qtr Panel osr  
Dented  
Over 30mm



14: Door osr  
Scratched  
Over 25mm Thru Paint



15: Door osf  
Dented  
2 Or Less UpTo 10mm



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK