



VEHICLE INSPECTION REPORT

LV15SYZ

Mazda CX-3 1.5d Sport Nav 5dr AWD Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	18/06/2015	VIN	JMZDKFWSA10102765	CAP Average	£4,075.00
Year	2015	Body Style	Hatchback	CAP Below	£3,400.00
Mileage	69,566 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Diesel	MOT Due	Expired	Gears	6
Colour	BLUE	CAP Clean	£4,750.00	Doors	5

MOT Expired

Spanner light on dash and tyre light and I-stop light on, alternator is noisy

Tyres


NSF	ACCELERA	Damaged
NSR	ACCELERA	6.0mm
OSF	LANVIGATOR	5.0mm
OSR	ACCELERA	6.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Telephone
- Air conditioning
- Rear headrests
- ESP
- Central locking
- Alloy wheels
- Cruise control
- PAS
- Radio/CD
- Climate control
- Metallic Paint
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Front electric windows
- ABS
- Traction control
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Qtr Panel Arch Extension os
Scuffed (Unpainted)
Over 100mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Door osr
Dented
Over 30mm



4: Reflector osr
Broken
Replace



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint

No Image



9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Wing nsf
Dented
2 Or Less UpTo 10mm



11: Bumper Front
Scratched
Over 100mm Thru Paint



12: Bonnet
Chipped
1 To 5



13: Wheel osf
Scratched
Over 50mm




14: Wheel osr
Scratched
Over 50mm



15: Wheel nsr
Scratched
Over 50mm



16: Wheel nsf
Scratched
Over 50mm



17: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK