



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GY64XAF**

## Mini Hatchback 1.5 Cooper 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	29/11/2014	Keys	2	CAP Clean	£4,100.00
Year	2014	Service history	Yes	CAP Average	£3,475.00
Mileage	82,018 Miles Warranted	Service documents	Printout	CAP Below	£2,850.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	11/11/2024	Gears	6
VIN	WMWXS520802B67911	Last service miles	79,520	Doors	5
Body Style	Hatchback	MOT Due	03/12/2025		

Last Service - 19.11.2024 at 79520 miles (2 services) Brake pad light on and possible exhaust leak

### Tyres

NSF	LAUFENN	4.0mm
NSR	MICHELIN	5.0mm
OSF	LAUFENN	3.0mm
OSR	LAUFENN	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Trip computer
- Electric door mirrors
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Radio/CD
- Air conditioning
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint






3: Screen Front  
Chipped  
UpTo 10mm




4: Wheel osf  
Scratched  
Over 50mm



5: Door osf  
Chipped  
1 To 5



6: Door osr  
Scratched  
Over 25mm Not Thru Paint




7: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint




8: Wheel osr  
Scratched  
Over 50mm



9: Bumper Rear  
 Scratched  
 Over 100mm Thru Paint



10: Boot Lid  
 Scratched  
 Over 25mm Not Thru Paint




11: Qtr Panel nsr  
 Scratched  
 Over 25mm Not Thru Paint



12: Wheel nsr  
 Scratched  
 Up To 50mm



13: Door nsr  
 Scratched  
 Over 25mm Not Thru Paint



14: Door nsf  
 Scratched  
 UpTo 25mm Not Thru Paint

No Image



15: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

16: Wheel nsf  
Scratched  
Over 50mm



17: Qtr Panel osr  
Dented  
Over 30mm

## Interior

Carpet Condition Average  
Seat Condition Average

Upholstery Condition Average  
Odour No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Turbo Boosting	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK



EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK