



## VEHICLE INSPECTION REPORT

**LO63TYD**

### Hyundai IX35 1.7 CRDi Blue Drive Premium Panorama 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



#### Details

Reg. date	14/01/2014	Body Style	Estate	MOT Due	14/03/2026
Year	2014	Keys	2	CAP Clean	£1,725.00
Mileage	126,936 Miles Warranted	Service history	Yes	CAP Average	£1,325.00
Fuel Type	Diesel	Service documents	Service Book	CAP Below	£925.00
Colour	BLACK	Number of stamps	3	Gearbox	MANUAL
VIN	TMAJU81ULEJ540803	Last service miles	84,767	Gears	6

£100 ADDITIONAL FEE. Last service date not recorded at 84767 miles (3 services (2 main dealer). Smokes  
Burning smells  
Roof not working

#### Tyres


NSF	MAXTREK	4.0mm
NSR	MAXTREK	5.0mm
OSF	BUDGET	4.0mm
OSR	MAXTREK	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint






3: Wheel nsf  
Scratched  
Up To 50mm



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsr  
Scratched  
Over 25mm Thru Paint



6: Qtr Panel nsr  
Dented  
With Paint Damage



7: Wheel nsr  
Scratched  
Over 50mm



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint





9: Wheel osr  
Scratched  
Over 50mm



10: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint



11: Door osr  
Dented  
With Paint Damage



12: Door osf  
Poor Previous Repair  
Rippled UpTo 30%



13: Wheel osf  
Scratched  
Over 50mm



14: Wing osf  
Scratched  
Over 25mm Thru Paint



15: Seat Base Cover osf  
Scuffed  
Over 25mm



16: Bonnet  
Rusted  
Holed

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		