



VEHICLE INSPECTION REPORT

LS14TYV

Mazda 3 2.0 SE-L 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 22/04/2014

Year 2014

Mileage 106,682 Miles
Warranted

Fuel Type Petrol

Colour BLUE

VIN JMZBM546611136423

Body Style Hatchback

Keys 2

Service history Yes

Service documents Printout

Number of stamps 9

Last service date 07/08/2025

Last service miles 106,294

MOT Due 06/08/2026

CAP Clean £3,150.00

CAP Average £2,600.00

CAP Below £2,075.00

Gearbox MANUAL

Gears 6

Doors 5

£100 ADDITIONAL FEE

Last service 07/08/2025 at 07/08/2025 106,294 miles- 9 services (4 main dealer)

Tyres

NSF BUDGET 4.0mm

NSR HANKOOK 4.0mm

OSF BUDGET 4.0mm

OSR HANKOOK 4.0mm


Spare

Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5

No Image

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




13: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Chipped
1 To 5



16: Boot Lid
Scratched
Over 25mm Not Thru Paint



17: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



18: Door osr
Chipped
1 To 5



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Roof
Chipped
1 To 5



23: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



24: Wing osf
Chipped
Multiple Chips



25: A Post os
Dented
Over 2 UpTo 10mm



26: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK