



# VEHICLE INSPECTION REPORT

**LM62SKZ**

## Nissan Juke 1.6 Shiro 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	15/11/2012	Keys	2	CAP Clean	£2,525.00
Year	2012	Service history	Yes	CAP Average	£2,075.00
Mileage	90,787 Miles Warranted	Service documents	Printout	CAP Below	£1,625.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLACK	Last service date	24/01/2024	Gears	5
VIN	SJNFBAF15U6309868	Last service miles	76,167	Doors	5
Body Style	Hatchback	MOT Due	14/11/2025		

Last Service - 24.01.2024 at 76167 miles (2 services) Slight suspension knock

### Tyres

NSF	BUDGET	2.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wing nsf  
Chipped  
1 To 5

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsf  
Dented  
With Paint Damage



8: Door nsr  
Chipped  
1 To 5

No Image

9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm

No Image

11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Bumper Rear  
Chipped  
Multiple Chips

No Image

13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



14: Boot Lid  
Dented  
Over 2 UpTo 10mm



No Image



15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Chipped  
1 To 5

No Image

18: Door osr  
Scratched  
Over 25mm Not Thru Paint




19: Door osf  
Chipped  
Multiple Chips



20: Door Mirror Assy osf  
Scratched (Painted)  
UpTo 25mm Thru Paint



21: Wing osf  
Chipped  
1 To 5



22: Wing osf  
Scratched  
Over 25mm Not Thru Paint



23: Wheel osf  
Scratched  
Up To 50mm



24: A Post os  
Poor Previous Repair  
Paint Flake



25: Seat Base Cover osf  
Torn  
UpTo 3mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK