



VEHICLE INSPECTION REPORT

ND14WUE

Nissan X-Trail 2.0 dCi N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/06/2014	Body Style	Estate	Last service miles	99,381
Year	2014	Keys	2	MOT Due	24/06/2026
Mileage	165,825 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	SILVER	Number of stamps	3		
VIN	JN1TCNT31U0413152	Last service date	27/01/2022		

£100 ADDITIONAL FEE

Last service 27/01/2022 at 99,381 miles- 3 services (2 main dealer) Vibration at idle and sun roof intermittent fault

Tyres

NSF	BRIDGESTONE	4.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear electric windows
- ABS
- Central locking

Photos






Condition Check



Damage Photos




1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5



4: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Scratched
Up To 50mm



8: Door osr
Chipped
1 To 5

No Image



9: Door osr
Scratched
Over 25mm Not Thru Paint

10: Door osf
Chipped
1 To 5



11: Wing osf
Chipped
1 To 5



12: Roof
Rusted
Over 5mm



13: Wheel osf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips



16: Wheel nsf
Scratched
Over 50mm



17: Wing nsf
Dented
Over 30mm



18: Door nsf
Dented
Over 30mm



19: Door Moulding nsf
Broken
Replace




20: Door nsr
Dented
Over 30mm



21: Wheel nsr
Scratched
Over 50mm



22: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



23: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



24: Bumper Rear Moulding
Broken
Replace



25: Carpets Front
Torn
Over 10mm



26: Headrest Assy Rear Seat ns
Missing
Replace

Interior

Carpet Condition
Seat Condition

Poor
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		