

46 Brampton Road Eastbourne BN229BN 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT



Kia Sportage 2.0 CRDi KX-3 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		
		V5	Present		
Details					
Reg. date	31/10/2016	Keys	2	CAP Clean	£7,100.00
Year	2016	Service history	Yes	CAP Average	£6,225.00
Mileage	91,983 Miles Warranted	Service documents	Service Book	CAP Below	£5,375.00
		Number of stamps	9	Gearbox	AUTOMATIC
Fuel Type	Diesel	Last service date	08/04/2025	Gears	6
Colour	WHITE	Last service miles	91,540		
VIN	U5YPH813SGL168353		30/10/2025		
Body Style	Estate		00, 0, 2020		

£100 ADDITIONAL FEE Last service 08/04/2025 @ 91540 miles (9 MAIN DEALER SERVICES)

Tyres			
NSF	AVON	3.0mm	
NSR	AVON	4.0mm	
OSF	AVON	3.0mm	
OSR	AVON	ОК	
Spare			

Features

- Bluetooth connection
- PAS
- Telephone Electric door mirrors
- Front armrest
- Rear electric windows
- 3x3 point rear seat belts
- Passenger airbag
 Remote central locking

Eastbourne Car Auctions

- Cruise control
- Rear parking sensor Audio remote control
- Space saver spare wheel Front electric windows
- Rear headrests
- ABS ٠
- Rear airbags
- Leather seat trim
- Heated front seat
 - Rear wiper
 - Digital radio
 - Air conditioning Front head restraints .
 - •
 - Steering wheel rake adjustment Drivers airbag •
 - Traction control
 - Alloy wheels

- Navigation system Steering wheel mounted controls Body coloured bumpers
- .
 - Climate control •
 - Height adjustable drivers seat
 - Solid Paint ٠
 - Isofix child seat anchor points
 - · Central locking

Photos






















Condition Check



Damage Photos







2: Bumper Front Chipped Multiple Chips



No Image

No Image

3: Wheel osf Scratched Over 50mm 4: Door osf Scratched Over 25mm Not Thru Paint



6: Wheel osr Scratched Over 50mm



8: Wheel nsr Scratched Over 50mm

5: Door osr Scratched Over 25mm Not Thru Paint



7: Bumper Rear Chipped Multiple Chips

No Image



9: Door nsr Scratched Over 25mm Not Thru Paint

10: Door nsf Chipped 1 To 5



11: Wheel nsf Scratched Over 50mm

Interior

Carpet Condition Seat Condition Average Average Upholstery Condition Odour Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK

EML light illuminated OK	Oil warning light illuminated OK
Airbag light illuminated OK	DPF light illuminated OK
ABS light illuminated OK	Service indicator light illuminated OK
Windows	Radio OK
	RadioOKSteeringOK