



VEHICLE INSPECTION REPORT

GX63FXZ

Honda Civic 1.8 i-VTEC Ti 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date	01/09/2013	VIN	SHHFK2740DU001849	CAP Average	£2,400.00
Year	2013	Body Style	Hatchback	CAP Below	£1,950.00
Mileage	114,686 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	31/08/2026	Gears	6
Colour	RED	CAP Clean	£2,850.00	Doors	5

Last Service - 11.08.2025 at 114487 miles (12 main dealer services) Front suspension knock


Tyres


NSF	AUTOGREEN	2.0mm
NSR	NEXEN	3.0mm
OSF	NEXEN	3.0mm
OSR	NEXEN	3.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- PAS
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint




3: Wheel nsf
 Scratched
 Over 50mm



4: Wing nsf
 Dented
 Over 2 UpTo 10mm




5: Door nsf
 Chipped
 1 To 5



6: Door nsf
 Scratched
 Over 25mm Not Thru Paint



7: Door nsr
 Chipped
 1 To 5



8: Door nsr
 Scratched
 Over 25mm Not Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Poor Previous Repair
Poor Paint



13: Qtr Panel osr
Chipped
1 To 5



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Thru Paint



17: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Seat Base Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK