



# VEHICLE INSPECTION REPORT

**VK60XOL**

## Suzuki Grand Vitara 1.6 VVT SZ4 3dr

**Non Runner**  
Inspection

Vehicle	
Serious Damage?	No
VAT	Margin
V5	Present



### Details

Reg. date	01/01/2011	Keys	2	CAP Clean	£2,125.00
Year	2011	Service history	Yes	CAP Average	£1,675.00
Mileage	69,397 Miles Warranted	Service documents	Service Book	CAP Below	£1,225.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	GREY	Last service date	21/09/2017	Gears	5
VIN	JSAJTA74V00611719	Last service miles	37,830		
Body Style	Estate	MOT Due	01/04/2026		

NON-RUNNER.

Last service 21/09/2017 at 37830 miles (7 main dealer services) Engine taken apart

### Tyres

NSF	YOKOHAMA	4.0mm
NSR	YOKOHAMA	4.0mm
OSF	YOKOHAMA	4.0mm
OSR	YOKOHAMA	5.0mm
Spare		

## Features


- PAS
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Passenger airbag
- Alloy wheels
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Curtain airbags
- Central locking
- Radio/CD
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5




2: Bumper Front  
Poor Previous Repair  
Poor Colour





3: Wing nsf  
Chipped  
1 To 5



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
1 To 5



7: Door nsf  
Scratched  
Up To 25mm Not Thru Paint



8: Qtr Panel nsr  
Dented  
Over 30mm



9: Bumper Rear  
Dented  
With Paint Damage



10: Boot Lid  
Dented  
Over 30mm



11: Wing osf  
Scratched  
Over 25mm Thru Paint



12: Wheel osf  
Scratched  
Over 50mm



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Qtr Panel osr  
Chipped  
1 To 5



No Image



15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osr  
Scratched  
Up To 50mm



17: Wheel nsr  
Scratched  
Up To 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	Fault	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	Fault

EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	Fault	Service indicator light illuminated	Fault
ABS light illuminated	Fault		
Windows	Fault	Radio	Fault
		Steering	Fault