



VEHICLE INSPECTION REPORT

GU10WHJ

Peugeot 207 1.6 HDi Verve 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2010	Keys	1	CAP Clean	£480.00
Year	2010	Service history	Yes	CAP Average	£200.00
Mileage	85,392 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	9	Gearbox	MANUAL
Colour	GREY	Last service date	21/02/2024	Gears	5
VIN	VF3WA9HXCAE007278	Last service miles	79,409	Doors	3
Body Style	Hatchback	MOT Due	08/12/2025		

£65 ADDITIONAL FEE LAST SERVICE 21/2/24 @ 79,409 MILES (9 SERVICES 2 MAIN DEALER) BOOK AND PRINT Engine noise exhaust faulty Smoking

Tyres

NSF	MICHELIN	5.0mm
NSR	BUDGET	5.0mm
OSF	MICHELIN	5.0mm
OSR	BUDGET	5.0mm

Spare

Features


- Bluetooth connection
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door osf
Dented
With Paint Damage



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Dented
With Paint Damage



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Qtr Panel osr
Dented
Over 30mm



12: Door osf
Dented
Over 30mm



13: Roof
Scratched
Rusted



14: Door Mirror Assy osf
Broken
Replace



15: A Post os
Dented
Between 10mm + 30mm



16: Screen Front
Chipped
UpTo 10mm



17: Wheel osf
Scratched
Up To 50mm



18: Wing osf
Scratched
Over 25mm Thru Paint



19: Front TowEye Cvr
Missing
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	Fault
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK