



VEHICLE INSPECTION REPORT

SM12NFR

Vauxhall Astra 1.6i 16V SRi 5dr

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
5

Details

Reg. date	31/05/2012	Body Style	Hatchback	Last service miles	90,408
Year	2012	Keys	2	MOT Due	18/02/2026
Mileage	91,826 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	10	Doors	5
VIN	W0LPF6ED4CG106523	Last service date	25/01/2025		

LAST SERVICE 25/1/25 @ 90,408 MILES (10 SERVICES 5 MAIN DEALER) BOOK AND PRINT
TIMING BELT REPLACED ON 3/4/24 @ 85,835 MILES Exhaust blowing and coolant leak

Tyres

NSF	BUDGET	5.0mm
NSR	TOYO	5.0mm
OSF	BUDGET	5.0mm
OSR	TOYO	5.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Metallic Paint
- ESP
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Door nsr
Scratched
Over 25mm Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Tailgate
Dented
With Paint Damage



9: Bumper Rear
Poor Previous Repair
Poor Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Dented
Over 30mm



12: Door osf
Scratched
Over 25mm Thru Paint



13: Roof
Scratched
Over 25mm Thru Paint



14: Wheel osf
Scratched
Up To 50mm



15: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK