



VEHICLE INSPECTION REPORT

GY67Nzb

Vauxhall Corsa 1.4T [150] Black Edition 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/11/2017	Keys	2	CAP Clean	£5,000.00
Year	2017	Service history	Yes	CAP Average	£4,300.00
Mileage	60,552 Miles Warranted	Service documents	Service Book	CAP Below	£3,600.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	BLACK	Last service date	17/11/2020	Gears	6
VIN	W0V0XEP08J6014337	Last service miles	14,337	Doors	3
Body Style	Hatchback	MOT Due	29/11/2025		

£100 ADDITIONAL FEE. Last Service: 17/11/2020 at 14337 miles. (3 main dealer services) Engine noisy

Tyres

NSF	RAPID	4.0mm
NSR	RAPID	4.0mm
OSF	RAPID	5.0mm
OSR	RAPID	4.0mm
Spare		

Features


- Bluetooth connection
- Audio remote control
- Electric door mirrors
- Folding rear seats
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Auxiliary input socket
- Front fog lights
- Front electric windows
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- ABS
- Traction control
- Alloy wheels

Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing osf
Dented
Over 2 UpTo 10mm



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Chipped
Multiple Chips



6: Qtr Panel osr
Dented
With Paint Damage



7: Wheel osr
Scratched
Over 50mm



8: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image




10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Door nsf
Chipped
1 To 5



13: Wing nsf
Dented
With Paint Damage



14: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK