



VEHICLE INSPECTION REPORT

HJ13HLA

Volkswagen Caravelle 2.0 BiTDI Business 180 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/03/2013	Keys	1	CAP Clean	£11,000.00
Year	2013	Service history	Yes	CAP Average	£9,950.00
Mileage	177,333 Miles Warranted	Service documents	Service Book	CAP Below	£8,875.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	AUTOMATIC
Colour	BLUE	Last service date	08/07/2021	Gears	6
VIN	WV2ZZZ7HZDH069325	Last service miles	149,060		
Body Style	MPV	MOT Due	13/02/2026		

Last service 08/07/2021 at 149060 miles (11 services)

Tyres


NSF	CONTINENTAL	4.0mm
NSR	CONTINENTAL	5.0mm
OSF	GOODYEAR	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Towbar
- Front electric windows
- Metallic Paint
- ESP
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Dented
Between 10mm + 30mm



5: Door osr
Scratched
Over 25mm Thru Paint



6: Wheel osf
Scratched
Over 50mm



7: Wheel osr
Scratched
Up To 50mm



8: Qtr Panel osr
Chipped
1 To 5



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Dented
Over 30mm



12: Door nsr
Scratched
Over 25mm Thru Paint



13: Wheel nsf
Scratched
Up To 50mm



14: Wing nsf
Scratched
Over 25mm Thru Paint



15: Roof
Poor Previous Repair
Paint Flake



16: Seat Back Cover osf
Scuffed
Over 25mm



17: Headlamp ns
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK