



VEHICLE INSPECTION REPORT

YG13YTV

Volkswagen Golf 1.4 TSI SE 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	29/03/2013	Keys	2	CAP Average	£5,100.00
Year	2013	Service history	Yes	CAP Below	£4,275.00
Mileage	71,510 Miles Warranted	Service documents	Printout	Gearbox	SEMI AUTO
Fuel Type	Petrol	Number of stamps	4	Gears	7
Colour	BLUE	Last service date	20/11/2021	Doors	5
VIN	WVWZZZAUZDW083441	MOT Due	21/08/2025		
Body Style	Hatchback	CAP Clean	£5,950.00		


£100 ADDITIONAL FEE. Last Service: 20/11/2021 at not recorded miles. (4 main dealer services).

Tyres		
NSF	FALKEN	4.0mm
NSR	BRIDGESTONE	3.0mm
OSF	TOYO	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Trip computer
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
1 To 5



3: Wing osf
Dented
Between 10mm + 30mm




4: Wheel osf
Scratched
Over 50mm



5: Door osf
Chipped
1 To 5



6: Door osr
Dented
Between 10mm + 30mm




7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Wheel nsr
Scratched
Up To 50mm



14: Door nsr
Dented
With Paint Damage



15: Door nsf
Chipped
1 To 5

16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK