



VEHICLE INSPECTION REPORT

KP57GZK

Mercedes-Benz S Class S320 CDI

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	07/11/2007	Body Style	Saloon	Last service miles	69,538
Year	2007	Keys	2	MOT Due	01/12/2025
Mileage	90,143 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	BLUE	Number of stamps	10	Doors	4
VIN	WDD2210222A187561	Last service date	08/11/2021		

LAST SERVICE 8/11/21 @ 69,538 MILES (10 SERVICES 2 MAIN DEALER) BOOK AND PRINT

Tyres

NSF	BUDGET	6.0mm
NSR	LAUFENN	3.0mm
OSF	BUDGET	6.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- Curtain airbags
- Rear airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Central locking
- Navigation system
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Wheel nsr
Scratched
Over 50mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Dented
With Paint Damage



11: Boot Lid
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Scratched
UpTo 25mm Thru Paint



17: Roof
Scratched
UpTo 25mm Thru Paint



18: Centre Console Front
Scuffed
Over 25mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK		
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		