



# VEHICLE INSPECTION REPORT

**SD68KKJ**

## Renault Captur 0.9 TCE 90 GT Line 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/09/2018	Keys	2	CAP Average	£5,125.00
Year	2018	Service history	Yes	CAP Below	£4,325.00
Mileage	61,374 Miles Warranted	Number of stamps	2	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	10/02/2022	Gears	5
Colour	BLACK/CREAM	Last service miles	20,248	Doors	5
VIN	VF1R8700961255353	MOT Due	12/02/2026		
Body Style	Hatchback	CAP Clean	£5,950.00		

Abs and traction control light on  
Vibration while revving

### Tyres

NSF	NANKANG	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	NANKANG	3.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Front electric windows
- Central locking
- Cruise control
- Rear parking sensor
- Rear electric windows
- Leather seat trim
- Front parking sensor
- Digital radio
- Drivers airbag
- Navigation system
- Air conditioning
- Passenger airbag

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips

No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wing osf  
Chipped  
1 To 5

No Image

5: Wing osf  
Scratched  
Over 25mm Not Thru Paint



6: Wheel osf  
Scratched  
Over 50mm




7: Door osf  
Chipped  
1 To 5

No Image

8: Door osf  
Scratched  
Over 25mm Not Thru Paint



9: Door osr  
Dented  
Between 10mm + 30mm



10: Door osr  
Scratched  
Over 25mm Not Thru Paint




11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Bumper Rear  
Chipped  
Multiple Chips

No Image

15: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



16: Boot Lid  
Dented  
Between 10mm + 30mm

No Image

17: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



18: Wheel nsr  
Scratched  
Over 50mm



19: Door nsr  
Chipped  
1 To 5

No Image


20: Door nsr  
Scratched  
Over 25mm Not Thru Paint



21: Door nsf  
Chipped  
Multiple Chips



22: Wing nsf  
Chipped  
1 To 5



23: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



24: Wheel nsf  
Scratched  
Over 50mm

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK