



# VEHICLE INSPECTION REPORT

**KY12KXL**

## Seat Alhambra 2.0 TDI CR Ecomotive SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	09/03/2012	Keys	2	CAP Clean	£3,325.00
Year	2012	Service history	Yes	CAP Average	£2,800.00
Mileage	115,104 Miles Warranted	Service documents	Service Book	CAP Below	£2,300.00
Fuel Type	Diesel	Number of stamps	12	Gearbox	MANUAL
Colour	BLACK	Last service date	21/01/2025	Gears	6
VIN	VSSZZZ7NZCV509262	Last service miles	113,463		
Body Style	MPV	MOT Due	28/01/2026		

£65 ADDITIONAL FEE Last service 21/01/2025 @ 113463 miles (12 SERVICES (4 MAIN DEALER)) Osr wheel arch trim insecure

### Tyres

NSF	BUDGET	3.0mm
NSR	SUNNY	4.0mm
OSF	BUDGET	2.0mm
OSR	SUNNY	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Radio/CD
- Climate control
- Rear electric windows
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Telephone
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Central locking
- PAS
- Trip computer
- Electric door mirrors
- Front head restraints
- Solid Paint
- Passenger airbag
- Remote central locking
- Rear wiper
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim

## Photos






## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint



2: Bumper Front  
Scratched  
Over 100mm Thru Paint






3: Screen Front  
Chipped  
UpTo 10mm




4: Wing nsf  
Chipped  
1 To 5




5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint



8: Door nsf  
Dented  
Over 2 UpTo 10mm

No Image



9: Door nsf  
Scratched  
Over 25mm Not Thru Paint

10: Door nsr  
Dented  
With Paint Damage



11: Qtr Panel nsr  
Dented  
Over 30mm



12: Bumper Rear  
Scratched  
Over 100mm Thru Paint



13: Boot Lid  
Chipped  
1 To 5




14: Qtr Panel osr  
Chipped  
1 To 5





15: Door osr  
Dented  
With Paint Damage



16: Door osf  
Dented  
Over 2 UpTo 10mm



17: Wheel osf  
Scratched  
Over 50mm



18: Wheel osr  
Scratched  
Over 50mm



19: Wheel nsr  
Scratched  
Over 50mm



20: Lamp osr  
Broken  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK