



VEHICLE INSPECTION REPORT

EY66UUE

Subaru XV 2.0i SE 5dr Lineartronic

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|---------------------------|--------------------|------------|-------------|-----------|
| Reg. date | 28/09/2016 | Keys | 2 | CAP Clean | £4,675.00 |
| Year | 2016 | Service history | Yes | CAP Average | £4,075.00 |
| Mileage | 92,374 Miles Warranted | Service documents | Printout | CAP Below | £3,475.00 |
| Fuel Type | Petrol | Number of stamps | 8 | Gearbox | CVT |
| Colour | WHITE | Last service date | 23/09/2024 | Gears | 6 |
| VIN | JF1GP7KC5GG175082 | Last service miles | 84,817 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 27/09/2025 | | |

Last service 23/09/2024 at 84,817 miles- 8 services

Tyres

| | | |
|-------|----------|-------|
| NSF | MICHELIN | 3.0mm |
| NSR | MICHELIN | 3.0mm |
| OSF | MICHELIN | 2.0mm |
| OSR | MICHELIN | 2.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Body coloured bumpers
- Towbar
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Door nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint




9: Wheel nsr
Scratched
Up To 50mm



10: Qtr Panel nsr
Chipped
1 To 5



11: Bumper Rear
Poor Previous Repair
Paint Flake



12: Boot Lid
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Chipped
1 To 5



14: Wheel osr
Scratched
Up To 50mm



15: Door osf
Dented
Over 2 UpTo 10mm



16: Wing osf
Chipped
1 To 5



17: Wheel osf
Scratched
Up To 50mm



18: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|---------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |