



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**KS66BFV**

## Skoda Fabia 1.2 TSI 90 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	21/11/2016	Keys	2	CAP Average	£4,225.00
Year	2016	Service history	Yes	CAP Below	£3,500.00
Mileage	57,999 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	08/03/2019	Gears	5
Colour	BLUE	Last service miles	25,422	Doors	5
VIN	TMBFM6NJ3HZ060140	MOT Due	16/03/2026		
Body Style	Hatchback	CAP Clean	£4,950.00		

£65 ADDITIONAL FEE Last service 08/03/2019 @ 25422 miles (3 MAIN DEALER SERVICES) Slight tapping from engine

### Tyres

NSF	YOKOHAMA	3.0mm
NSR	YOKOHAMA	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	YOKOHAMA	4.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Rear parking sensor
- Audio remote control
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing osf  
Scratched  
Over 25mm Thru Paint




4: Wheel osf  
Scratched  
Over 50mm



5: Door osf  
Chipped  
1 To 5



6: Door osr  
Chipped  
1 To 5



7: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



8: Wheel osr  
Scratched  
Over 50mm



9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



11: Wheel nsr  
Scratched  
Over 50mm



12: Door nsr  
Dented  
With Paint Damage



13: Door nsf  
Chipped  
1 To 5



14: Wing nsf  
Dented  
Over 30mm





15: Wheel nsf  
Scratched  
Over 50mm

16: A Post os  
Dented  
Between 10mm + 30mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK