



VEHICLE INSPECTION REPORT

LL66PDK

Renault Captur 0.9 TCE 90 Dynamique S Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	30/11/2016	Keys	2	CAP Average	£3,450.00
Year	2016	Service history	Yes	CAP Below	£2,900.00
Mileage	72,588 Miles Warranted	Service documents	Service Book	Gearbox	MANUAL
Fuel Type	Petrol	Number of stamps	7	Gears	5
Colour	BLUE/BLACK	Last service date	14/04/2025	Doors	5
VIN	VF12RD11A56719401	MOT Due	29/11/2025		
Body Style	Hatchback	CAP Clean	£4,025.00		

Last Service - 14.04.2025 at unknown miles (services) Noisy engine

Tyres

NSF	LAUFENN	2.0mm
NSR	AVON	4.0mm
OSF	LAUFENN	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Radio/CD
- Front fog lights
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Telephone
- USB/iPod interface
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
Multiple Chips

No Image



3: Wing nsf
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Corroded
Light



5: Door nsf
Scratched
Over 25mm Thru Paint

6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

8: Wheel nsr
Corroded
Light

No Image



9: Bumper Rear
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Chipped
1 To 5



11: Wheel osr
Corroded
Light

No Image

12: Door osr
Scratched
Over 25mm Not Thru Paint

No Image

13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Wheel osf
Corroded
Light

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
-

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK