

VEHICLE INSPECTION REPORT

GV610PG

Volkswagen Golf 1.4 TSI SE 5dr

		V5	Present
Serious Damage?	No	VAT	Margin
inspection		venicie	



Details

Reg. date	28/09/2011	Body Style	Hatchback	Last service miles	22,761
Year	2011	Keys	2	MOT Due	28/09/2025
Mileage	23,685 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	13	Doors	5
VIN	WVWZZZ1KZCP017847	Last service date	20/09/2024		

Last Service - 20.09.2024 at 22761 miles (13 services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- · Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- · Drivers airbag
- Rear airbags Cloth seat trim
- · Cruise control
- Rear wiper
- Electric door mirrors
- Folding rear seats Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels

- · Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front armrest Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD Space saver spare wheel
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking

Photos










Condition Check



Damage Photos



1: Bonnet Scratched Over 25mm Thru Paint



2: Bumper Front Dented With Paint Damage



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Door nsf Scratched Over 25mm Thru Paint



6: Door nsr Scratched UpTo 25mm Thru Paint



7: Wheel nsr Scratched Over 50mm



8: Qtr Panel nsr Scratched Over 25mm Thru Paint



9: Bumper Rear Scratched 25 to 100mm Thru Paint



10: Tailgate Scratched UpTo 25mm Thru Paint



11: Qtr Panel osr Scratched Over 25mm Thru Paint



12: Door osr Scratched UpTo 25mm Thru Paint



13: Door osf Chipped Edge Chip



14: Wheel osf Scratched Over 50mm



15: Wing osf Scratched Over 25mm Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
		, , , , , , , , , , , , , , , , , , ,	
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK