



# VEHICLE INSPECTION REPORT

**GX20KPV**

## Volvo XC40 1.5 T3 [163] Momentum 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	02/03/2020	Keys	2	CAP Clean	£15,650.00
Year	2020	Service history	Yes	CAP Average	£14,300.00
Mileage	31,299 Miles Warranted	Service documents	Service Book	CAP Below	£12,950.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	GREY	Last service date	21/03/2025	Gears	6
VIN	YV1XZ11V1L2307327	Last service miles	29,064		
Body Style	Estate	MOT Due	20/03/2026		

Last Service - 21.03.2025 at 29064 miles (5 services)

### Tyres


NSF	MICHELIN	6.0mm
NSR	MICHELIN	6.0mm
OSF	MICHELIN	6.0mm
OSR	MICHELIN	6.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Roof Lining  
Soiled  
Light



2: Bonnet  
Chipped  
1 To 5





3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
UpTo 25mm Thru Paint



9: Bumper Rear  
Scratched  
Up To 25mm Thru Paint



10: Door osr  
Poor Previous Repair  
Rippled UpTo 30%



11: Door osf  
Poor Previous Repair  
Poor Paint




12: Wing osf  
Scratched  
UpTo 25mm Thru Paint



13: Wheel osf  
Scratched  
Over 50mm



14: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



15: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK