



VEHICLE INSPECTION REPORT

WJ66XRD

Ford B-Max 1.6 Zetec 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/10/2016	Keys	2	CAP Clean	£4,775.00
Year	2016	Service history	Yes	CAP Average	£4,075.00
Mileage	28,924 Miles Warranted	Service documents	Service Book	CAP Below	£3,400.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	AUTOMATIC
Colour	GREY	Last service date	18/12/2020	Gears	5
VIN	WF0KXXERJKGL51712	Last service miles	6,850		
Body Style	MPV	MOT Due	14/01/2026		

LAST SERVICE 18/12/20 @ 6850 MILES (4 SERVICES 2 MAIN DEALER) BOOK AND PRINT

Tyres

NSF	COMFORSER	5.0mm
NSR	GOODYEAR	5.0mm
OSF	COMFORSER	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- PAS
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Door nsf
Dented
With Paint Damage



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Qtr Panel osr
Dented
With Paint Damage



11: Wheel osr
Scratched
Up To 50mm



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
With Paint Damage



14: Wing osf
Scratched
UpTo 25mm Thru Paint



15: Flasher Side Repeater os
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK