

## **VEHICLE INSPECTION REPORT**

DG24ECY

## Seat Ateca 1.5 TSI EVO Xperience Lux 5dr DSG

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape.
		V5	Present		
Details					
Reg. date	12/03/2024	Keys	2	CAP Clean	£21,800.00
Year	2024	Service history	Yes	CAP Average	£20,400.00
Mileage	13,043 Miles Warranted	Service documents	Printout	CAP Below	£19,000.00
		Number of stamps	1	Gearbox	SEMI AUTO
Fuel Type	Petrol	Last service date	03/06/2025	Gears	7
Colour	GREY	Last service miles	9,582	Doors	5
VIN	VSSZZZ5FXR6545047	MOT Due	11/03/2027		
Body Style	Hatchback				

Last Service - 03.06.2025 at 9582 miles (1 services)

NSF	UNIROYAL	6.0mm	
NSR	HANKOOK	5.0mm	
OSF	UNIROYAL	6.0mm	
OSR	HANKOOK	5.0mm	_
Spare			

### **Features**

- Bluetooth connection
- Navigation systemRear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbagsAlloy wheels

- Cruise control
- Park assist camera

- Drivers airbag
- Steering wheel mounted controls
  Front fog lights
  Front electric windows

   Digital radio
   Air conditioning
   Front head restraints

- Rear headrests
- Central locking
- · Front parking sensor
- PAS

- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat

- Rear parking sensor
  Body coloured bumpers
  Folding rear seats
  Height adjustable drivers seat
  3x3 point rear seat belts
- Passenger airbag
- Leather seat trim

### **Photos**










# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint



3: Door nsf Scratched Over 25mm Thru Paint



4: Bumper Rear Moulding Scuffed (Unpainted) UpTo 100mm



5: Bumper Rear Scratched Up To 25mm Thru Paint



6: Qtr Panel osr Scratched UpTo 25mm Thru Paint



7: Door osr Scratched Over 25mm Thru Paint



8: Door osf Scratched UpTo 25mm Thru Paint



9: Wing osf Scratched UpTo 25mm Thru Paint

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK