

### **VEHICLE INSPECTION REPORT**

# **RE68HNA**

## Mitsubishi Eclipse Cross 1.5 3 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape 3
		V5	Present		
Details					
Reg. date	31/10/2018	Keys	2	CAP Clean	£8,675.00
Year	2018	Service history	Yes	CAP Average	£7,675.00
Mileage	32,629 Miles Warranted	Service documents	Service Book	CAP Below	£6,675.00
		Number of stamps	3	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	28/07/2025	Gears	6
Colour	RED	Last service miles	32,445	Doors	5
VIN	JMAXJGK1WJZ002812	MOT Due	05/01/2026		
Body Style	Hatchback				

Last Service - 28.07.2025 at 32445 miles (3 services)

•	VIES
-	,

NSF	HANKOOK	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	HANKOOK	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

### **Features**

- Bluetooth connection
- Park assist camera
- Digital radio
- Towbar
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbagsAlloy wheels

- Cruise control
- PAS
- Body coloured bumpers Air conditioning Front head restraints

- Metallic Paint
- ESP
- · Central locking
- Front parking sensor


- Front parking sensor
  Rear parking sensor
  Electric door mirrors
  Folding rear seats
  Height adjustable drivers seat
  3x3 point rear seat belts
  Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
   Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim

#### **Photos**










# **Condition Check**



### **Damage Photos**




1: Bumper Front Scratched Over 100mm Thru Paint



2: Wheel nsf Scratched Over 50mm



3: Bumper Front Insecure Action Required



4: A Post ns Scratched UpTo 25mm Thru Paint



5: Door nsf Dented Between 10mm + 30mm



6: Bumper Rear Scratched Up To 25mm Thru Paint



7: Qtr Panel osr Scratched Over 25mm Thru Paint



8: Door osr Chipped 1 To 5



9: Door osf Chipped Edge Chip



10: Door Mirror Assy osf Scratched (Painted) UpTo 25mm Thru Paint



11: Roof Scratched Over 25mm Thru Paint

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

#### **Vehicle Inspection Report**

#### **Disclaimer**

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OI	Gearbox 1st and Reverse Test	OK
Brakes OI	Clutch Slip Test from Static	OK
Parking Brake OI	Gearbox Static Gear Selection (engine running)	OK
	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK