



VEHICLE INSPECTION REPORT

HD62AOB

Land Rover Freelander 2.2 SD4 HSE LUX 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	22/10/2012	Keys	2	CAP Clean	£3,850.00
Year	2012	Service history	Yes	CAP Average	£3,350.00
Mileage	136,490 Miles Warranted	Service documents	Printout	CAP Below	£2,800.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	20/07/2025	Gears	6
VIN	SALFA2AEXDH322920	Last service miles	135,766		
Body Style	Estate	MOT Due	27/03/2026		

LAST SERVICE 20/7/25 @ 135,766 MILES (7 SERVICES 5 MAIN DEALER) PRINT
NEW TIMING CHAIN AND CYLINDER HEAD FITTED ON 27/3/24 @ 128,570 MILES

Tyres		
NSF	MICHELIN	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric sunroof
- Electrically adjustable passenger seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Lane departure warning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Wheel osr
Scratched
Up To 50mm



11: Door osr
Chipped
Edge Chip



12: Door osf
Chipped
Edge Chip



13: Wheel osf
Dented
Up To 30mm (Alloy)



14: Tailgate
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		