



VEHICLE INSPECTION REPORT

E071JGZ

Ford Puma 1.0 EcoBoost Hybr mHEV 155 ST-Line Vignale 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/09/2021	Keys	2	CAP Clean	£16,300.00
Year	2021	Service history	Yes	CAP Average	£14,950.00
Mileage	23,777 Miles Warranted	Service documents	Printout	CAP Below	£13,600.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	AUTOMATIC
Colour	RED	Last service date	23/08/2025	Gears	7
VIN	WF02XXERK2MA56027	Last service miles	23,331	Doors	5
Body Style	Hatchback	MOT Due	01/09/2026		

LAST SERVICE 23/8/25 @ 23,331 MILES (3 SERVICES 1 MAIN DEALER) PRINT

Tyres



NSF	GOODYEAR	4.0mm
NSR	YOKOHAMA	5.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Opening panoramic glass roof
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim

Photos





Condition Check



Damage Photos




1: Bonnet
Scratched
UpTo 25mm Thru Paint




2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Scratched
Over 25mm Thru Paint




5: Door nsr
Scratched
UpTo 25mm Thru Paint



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Wheel osr
Scratched
Over 50mm



8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Door osr
 Scratched
 UpTo 25mm Thru Paint



10: Door osf
 Dented
 Between 10mm + 30mm



11: Wheel osf
 Scratched
 Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		