



# VEHICLE INSPECTION REPORT

LO22UUN

## Kia Stonic 1.0T GDi 48V GT-Line 5dr DCT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
3

### Details

Reg. date	28/07/2022	Keys	2	CAP Clean	£14,100.00
Year	2022	Service history	Yes	CAP Average	£12,850.00
Mileage	25,257 Miles Warranted	Service documents	Service Book	CAP Below	£11,600.00
Fuel Type	Hybrid Electric	Number of stamps	3	Gearbox	SEMI AUTO
Colour	GREY	Last service date	29/06/2025	Gears	7
VIN	KNADD817VN6705286	Last service miles	24,591	Doors	5
Body Style	Hatchback	MOT Due	28/07/2026		

Last Service - 29.07.2025 at 29591 miles (3 services)

### Tyres

NSF	CONTINENTAL	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
UpTo 25mm Thru Paint




2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm



4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
UpTo 25mm Thru Paint



7: Wheel osr  
Scratched  
Over 50mm




8: Door osr  
Scratched  
UpTo 25mm Thru Paint



9: Door osf  
Scratched  
Over 25mm Thru Paint



10: Wing osf  
Scratched  
UpTo 25mm Thru Paint



11: Roof  
Scratched  
Over 25mm Thru Paint

## Interior

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK