

## **VEHICLE INSPECTION REPORT**

**EP19BZU** 

### Ford Fiesta 1.0 EcoBoost 125 ST-Line X 5dr

inspection		venicie			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	10/06/2019	Keys	2	CAP Clean	£7,525.00
Year	2019	Service history	Yes	CAP Average	£6,625.00
Mileage	40,934 Miles Warranted	Service documents	Service Book	CAP Below	£5,725.00
Fuel Type	Petrol	Number of stamps	4	Gearbox	MANUAL
Colour	GREY	Last service date	09/06/2025	Gears	6
VIN	WF0JXXGAHJKL82876	Last service miles	39,011	Doors	5
Body Style	Hatchback	MOT Due	09/06/2026		

#### £65 ADDITIONAL FEE

Last service 09/06/2025 at 39,011 miles- 4 main dealer services

т	٠.		_	_
	У	ı	C	Э

NSF	CONTINENTAL	3.0mm	
NSR	BUDGET	3.0mm	
OSF	CONTINENTAL	3.0mm	
OSR	BUDGET	3.0mm	
Spare			

### **Features**

- Bluetooth connection
- Rear parking sensor
  Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
  ABS
- Passenger airbagCloth seat trim
- Cruise control
- Rear wiper Electric door mirrors
- Front armrest
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels

- Navigation system
   Steering wheel mounted controls
   Front fog lights
   Front electric windows


- Metallic Paint
   ESP
- Central locking
- PAS
- Digital radio
- Air conditioningFront head restraints
- 3x3 point rear seat belts
  Isofix child seat anchor points
- Remote central locking

### **Photos**










# **Condition Check**



## **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Chipped Multiple Chips


# No Image

3: Bumper Front Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

# No Image





6: Door nsf Dented Between 10mm + 30mm



7: Door nsr Scratched UpTo 25mm Thru Paint

# No Image

8: Door nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Up To 50mm



10: Qtr Panel nsr Dented 2 Or Less UpTo 10mm



11: Bumper Rear Scratched Over 25mm Not Thru Paint



12: Qtr Panel osr Dented 2 Or Less UpTo 10mm

# No Image

13: Qtr Panel osr Scratched Over 25mm Not Thru Paint



14: Wheel osr Scratched Up To 50mm



15: Door osr Chipped 1 To 5



16: Door osf Chipped 1 To 5

# No Image

17: Door osf Scratched Over 25mm Not Thru Paint



18: Wheel osf Scratched Up To 50mm

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	ОК
Sat nav	OK	Steering	OK