



VEHICLE INSPECTION REPORT

AO65OYU

Nissan Qashqai 1.2 DiG-T N-Tec+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	19/11/2015	Keys	2	CAP Clean	£4,600.00
Year	2015	Service history	Yes	CAP Average	£4,000.00
Mileage	54,303 Miles Warranted	Service documents	Service Book	CAP Below	£3,375.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	WHITE	Last service date	16/11/2021	Gears	6
VIN	SJNFEAJ11U1539988	Last service miles	36,178	Doors	5
Body Style	Hatchback	MOT Due	21/11/2025		

Last service 16/11/2021 at 36,178 miles- 7 services (2 main dealer) Tapping engine

Tyres


NSF	AVON	Worn
NSR	BUDGET	3.0mm
OSF	BUDGET	2.0mm
OSR	AVON	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Fixed panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Park assist camera
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5

No Image



5: Wing nsf
Scratched
Over 25mm Not Thru Paint

6: Door nsf
Chipped
Multiple Chips



7: Door nsr
Dented
Between 10mm + 30mm

No Image

8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsf
Scratched
Over 50mm




10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
Over 100mm Thru Paint



12: Boot Lid
Chipped
1 To 5




13: Boot Lid
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Dented
Between 10mm + 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Door osr
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		