



VEHICLE INSPECTION REPORT

RO69YBF

Hyundai Kona 150kW Premium 64kWh 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/11/2019	Keys	2	CAP Clean	£7,550.00
Year	2019	Service history	Yes	CAP Average	£6,600.00
Mileage	77,298 Miles Warranted	Service documents	Printout	CAP Below	£5,625.00
Fuel Type	Electric	Number of stamps	4	Gearbox	AUTOMATIC
Colour	RED	Last service date	29/05/2024	Gears	1
VIN	KMHK381GUKU053094	Last service miles	59,590	Doors	5
Body Style	Hatchback	MOT Due	02/12/2025		

£100 ADDITIONAL FEE

Last service 29/05/2024 at 59,590 miles- 4 main dealer services Radio need update, unable to check some features

Type 2 charging cable only

Tyres

NSF	HANKOOK	5.0mm
NSR	RAPID	6.0mm
OSF	HANKOOK	5.0mm
OSR	RAPID	6.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Between 10mm + 30mm



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel osf
Scratched
Up To 50mm



4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osr
Scratched
Up To 25mm Thru Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Tailgate Trim Panel
Scratched (Painted)
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Door nsr
Dented
Between 10mm + 30mm



12: Door nsf
Chipped
Edge Chip



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5



15: Roof
Chipped
Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	Fault
		Steering	OK