



# VEHICLE INSPECTION REPORT

**SV62WHH**

## Audi A1 1.4 TFSI S Line 5dr S Tronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	27/09/2012	Keys	1	CAP Clean	£4,700.00
Year	2012	Service history	Yes	CAP Average	£4,075.00
Mileage	94,367 Miles Warranted	Service documents	Service Book	CAP Below	£3,450.00
Fuel Type	Petrol	Number of stamps	12	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	31/03/2025	Gears	7
VIN	WAUZZZ8X0DB031016	Last service miles	91,001	Doors	5
Body Style	Hatchback	MOT Due	14/04/2026		

£65 ADDITIONAL FEE

Lasts service 31/03/2025 at 91,001 miles- 12 services (4 main dealer)

### Tyres


NSF	DUNLOP	2.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	2.0mm
Spare		

## Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- Curtain airbags
- Traction control
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- ESP
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Boot Lid  
Poor Previous Repair  
Poor Paint



2: Bumper Rear  
Poor Previous Repair  
Poor Paint





3: Qtr Panel nsf  
Dented  
Over 2 UpTo 10mm



4: Door nsf  
Chipped  
1 To 5



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Poor Previous Repair  
Poor Paint



7: Wing nsf  
Chipped  
1 To 5



8: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsf  
Scratched  
Over 50mm




10: Bonnet  
Poor Previous Repair  
Poor Paint



11: Bumper Front  
Poor Previous Repair  
Poor Paint



12: Wheel osf  
Scratched  
Over 50mm



13: Wing osf  
Scratched  
Over 25mm Not Thru Paint




14: Door osf  
Dented  
Over 2 UpTo 10mm





15: Door osr  
Chipped  
1 To 5



16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Qtr Panel osr  
Dented  
Between 10mm + 30mm



18: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



19: Wheel osf  
Scratched  
Over 50mm



20: Door Mirror Assy osf  
Broken  
Replace

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK