

VEHICLE INSPECTION REPORT

GU64GDJ

Mini Hatchback 1.5 Cooper 3dr

	Vehicle			nama
No	VAT	Margin		2 grape
	V5	Present		
10/09/2014	Keys	2	CAP Average	£3,775.00
2014	Service history	Yes	CAP Below	£3,200.00
63,398 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Petrol	Last service date	04/10/2024	Gears	6
BLUE	Last service miles	58,875	Doors	3
WMWXM52040T947714	MOT Due	30/10/2025		
Hatchback	CAP Clean	£4,350.00		
	10/09/2014 2014 63,398 Miles Warranted Petrol BLUE WMWXM52040T947714	No VAT V5 10/09/2014 Keys 2014 Service history 63,398 Miles Warranted Service documents Petrol Last service date BLUE Last service miles WMWXM52040T947714 MOT Due	No VAT Margin V5 Present 10/09/2014 Keys 2 2014 Service history Yes 63,398 Miles Warranted Service documents Printout Petrol Last service date 04/10/2024 BLUE Last service miles 58,875 WMWXM52040T947714 MOT Due 30/10/2025	No VAT Margin V5 Present 10/09/2014 Keys 2 CAP Average 2014 Service history Yes CAP Below 63,398 Miles Warranted Service documents Printout Gearbox Petrol Last service date 04/10/2024 Gears BLUE Last service miles 58,875 Doors WMWXM52040T947714 MOT Due 30/10/2025

ADDITIONAL FEE £65.00 Last service 4/10/2024 @ 58875 miles (1 SERVICE)

Tyres			
NSF	TOYO	3.0mm	
NSR	TOYO	3.0mm	
OSF	тоуо	4.0mm	
OSR	тоуо	3.0mm	
Spare			

Features

- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Rear headrests
- Partial leather seat trim
- Passenger airbag
- Cruise control
- Trip computer
- Electric door mirrors Front electric windows
- Solid Paint
- Traction control
- Alloy wheels

- PAS
- Audio remote control
- · Front fog lights
- Front head restraints
- Drivers airbag
- Central locking
- Rear wiper
- Radio/CD
- Air conditioning Height adjustable drivers seat
- Isofix child seat anchor points
- Remote central locking

Photos














Condition Check



Damage Photos



1: Screen Front Chipped UpTo 10mm




2: Bonnet Chipped 1 To 5



3: Bumper Front Chipped 1 To 5



4: Wheel nsf Scratched Over 50mm



5: Door nsf Chipped 1 To 5



6: Qtr Panel nsr Chipped 1 To 5

No Image





8: Bumper Rear Chipped Multiple Chips



9: Wheel osr Corroded Light

No Image

10: Qtr Panel osrScratchedOver 25mm Not Thru Paint

No Image

11: Door osfScratchedOver 25mm Not Thru Paint

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs C	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK