



VEHICLE INSPECTION REPORT

GU68XSX

Hyundai IX20 1.6 SE Nav 5dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

Details

Reg. date	29/09/2018	Keys	2	CAP Clean	£6,625.00
Year	2018	Service history	Yes	CAP Average	£5,775.00
Mileage	50,971 Miles Warranted	Service documents	Service Book	CAP Below	£4,925.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	MANUAL
Colour	GREEN	Last service date	27/07/2024	Gears	6
VIN	TMAPU81DLKJ294932	Last service miles	40,302		
Body Style	MPV	MOT Due	28/09/2025		

LAST SERVICE 27/7/24 @ 40,302 MILES (6 MAIN DEALER) BOOK

Tyres

NSF	CONTINENTAL	2.0mm
NSR	CONTINENTAL	Worn
OSF	CONTINENTAL	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm

No Image

6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
Between 10mm + 30mm



8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Bumper Rear
Insecure
Action Required



12: Parking Sensor Rear
Broken
Replace



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Door osr
Dented
Over 2 UpTo 10mm



16: Door osf
Chipped
1 To 5



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK