



VEHICLE INSPECTION REPORT

GV15LRA

Nissan Micra 1.2 Acenta 5dr CVT

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	26/06/2015	Keys	2	CAP Clean	£4,700.00
Year	2015	Service history	Yes	CAP Average	£4,050.00
Mileage	44,370 Miles Warranted	Service documents	Service Book	CAP Below	£3,400.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	CVT
Colour	RED	Last service date	08/05/2025	Gears	1
VIN	MDHFBUK13U0819310	Last service miles	43,327	Doors	5
Body Style	Hatchback	MOT Due	11/05/2026		

Last Service - 08.05.2025 at 43327 miles (9 services)

Tyres

NSF	TOYO	3.0mm
NSR	BRIDGESTONE	5.0mm
OSF	LAUFENN	3.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Digital radio
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Insurance telematics
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
With Paint Damage



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Wheel osr
Scratched
Over 50mm



12: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wheel osf
Scratched
Over 50mm



16: Wing osf
Scratched
Over 25mm Thru Paint



17: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



18: Roof
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK