

# VEHICLE INSPECTION REPORT

**MK13ZGS**

## Ford Fiesta 1.6 Titanium 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	17/03/2013	VIN	WF0DXXGAKDDU60586	CAP Average	£3,375.00
Year	2013	Body Style	Hatchback	CAP Below	£2,800.00
Mileage	59,395 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	29/01/2026	Gears	6
Colour	BLACK	CAP Clean	£3,950.00	Doors	5

£100 ADDITIONAL FEE Suspension knocking



### Tyres

NSF	GT RADIAL	4.0mm
NSR	GT RADIAL	4.0mm
OSF	GT RADIAL	2.0mm
OSR	GT RADIAL	4.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- ESP
- Remote central locking
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Radio/CD
- Climate control
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Poor Previous Repair  
Poor Paint



2: Bumper Front  
Chipped  
Multiple Chips



No Image



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsf  
Chipped  
Multiple Chips



7: Door nsr  
Chipped  
Multiple Chips




8: Wheel nsr  
Scratched  
Up To 50mm



9: Qtr Panel nsr  
Dented  
With Paint Damage



10: Bumper Rear  
Chipped  
Multiple Chips



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Dented  
Between 10mm + 30mm



13: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



14: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint





15: Wheel osr  
Scratched  
Up To 50mm




16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Poor Previous Repair  
Poor Paint



18: Wing osf  
Dented  
Between 10mm + 30mm



19: Wing osf  
Scratched  
Over 25mm Not Thru Paint



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK