

VEHICLE INSPECTION REPORT

KS63CVZ

Ford Fiesta 1.0 EcoBoost Titanium X 5dr Powershift

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	22/01/2014	VIN	WF0DXXGAKDDD27754	CAP Average	£4,325.00
Year	2014	Body Style	Hatchback	CAP Below	£3,675.00
Mileage	37,522 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	24/11/2025	Gears	6
Colour	RED	CAP Clean	£5,000.00	Doors	5

£100 ADDITIONAL FEE

Tyres

NSF	HIFLY	4.0mm
NSR	HIFLY	4.0mm
OSF	RAPID	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Heated front seat
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- ESP
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bonnet
Scratched
Over 25mm Not Thru Paint




3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Up To 50mm



5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel nsr
Chipped
1 To 5



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image


13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Chipped
1 To 5



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Chipped
Multiple Chips



19: Door osf
Chipped
Multiple Chips



20: D Post os
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Chipped
1 To 5



22: Screen Front
Chipped
UpTo 10mm



23: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK