



VEHICLE INSPECTION REPORT

CA65BZU

Volkswagen Golf Sv 1.6 TDI 110 SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
4

Details

Reg. date	11/12/2015	Keys	2	CAP Clean	£3,725.00
Year	2015	Service history	Yes	CAP Average	£3,175.00
Mileage	107,703 Miles Warranted	Service documents	Service Book	CAP Below	£2,600.00
Fuel Type	Diesel	Number of stamps	11	Gearbox	MANUAL
Colour	BLACK	Last service date	25/03/2025	Gears	5
VIN	WWWZZZAUZGW501626	Last service miles	103,316		
Body Style	MPV	MOT Due	10/12/2025		

£65 ADDITIONAL FEE

Last service 25/03/2025 at 103,316 miles- 11 services (3 main dealer)

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Scratched
UpTo 25mm Thru Paint

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Between 10mm + 30mm

No Image

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Bumper Rear
Scratched
Over 100mm Thru Paint




14: Boot Lid
Dented
Over 2 UpTo 10mm



15: Qtr Panel osr
Dented
With Paint Damage




16: Wheel osr
Scratched
Over 50mm



17: Door osr
Scratched
Over 25mm Not Thru Paint



18: Door osf
Chipped
1 To 5



19: Door osf
Scratched
Over 25mm Not Thru Paint



20: Wing osf
Chipped
1 To 5



21: Wheel of
Scratched
Over 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK