



VEHICLE INSPECTION REPORT

GY17YGO

Land Rover Discovery Sport 2.0 TD4 180 HSE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	26/05/2017	Keys	2	CAP Clean	£8,825.00
Year	2017	Service history	Yes	CAP Average	£7,775.00
Mileage	55,556 Miles Warranted	Service documents	Printout	CAP Below	£6,700.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	AUTOMATIC
Colour	GREY	Last service date	21/12/2024	Gears	9
VIN	SALCA2AN4HH703977	Last service miles	50,643		
Body Style	Estate	MOT Due	07/01/2026		

£65 ADDITIONAL FEE  
Last service 21/12/2024 at 50,643 miles- 8 services (4 main dealer services)

Tyres		
NSF	PIRELLI	Worn
NSR	PIRELLI	4.0mm
OSF	PIRELLI	2.0mm
OSR	PIRELLI	4.0mm
Spare		

Features


- Bluetooth connection
  - Park assist camera
  - Steering wheel mounted controls
  - Electric door mirrors
  - Climate control
  - Front electric windows
  - Rear headrests
  - Curtain airbags
  - Passenger airbag
  - Remote central locking
- Cruise control
  - PAS
  - Audio remote control
  - Electric sunroof
  - Electrically adjustable drivers seat
  - Front head restraints
  - Metallic Paint
  - Drivers airbag
  - Side airbags
  - Leather seat trim
- Heated front seat
  - Rear parking sensor
  - Digital radio
  - Fixed panoramic glass roof
  - Electrically adjustable passenger seat
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - ESP
  - Traction control
  - Alloy wheels
- Navigation system
  - Rear wiper
  - Body coloured bumpers
  - Air conditioning
  - Front armrest
  - Rear electric windows
  - ABS
  - Isofix child seat anchor points
  - Central locking

Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm

No Image



5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint

6: Door nsf  
Dented  
Over 2 UpTo 10mm

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Over 50mm

No Image

10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Bumper Rear  
Chipped  
Multiple Chips

No Image

12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Bumper Rear Moulding  
Broken  
Replace

No Image

14: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint





15: Wheel osr  
Scratched  
Over 50mm



16: Door osr  
Dented  
Over 2 UpTo 10mm



17: Door osr  
Chipped  
1 To 5



18: Door osf  
Chipped  
Multiple Chips



19: Wing osf  
Chipped  
1 To 5



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		