



# VEHICLE INSPECTION REPORT

**GX14LEU**

## Volkswagen Golf 1.4 TSI SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	01/03/2014	Keys	1	CAP Clean	£4,900.00
Year	2014	Service history	Yes	CAP Average	£4,175.00
Mileage	75,481 Miles Warranted	Service documents	Service Book	CAP Below	£3,450.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	BLUE	Last service date	23/09/2024	Gears	6
VIN	WVWZZZAUZEW262745	Last service miles	68,842	Doors	5
Body Style	Hatchback	MOT Due	17/08/2026		

£65 ADDITIONAL FEE

Last service 23/09/2024 at 68,842 miles- 10 services (4 main dealer) Noisy front suspension when braking

### Tyres



NSF	LAUFENN	5.0mm
NSR	GOODYEAR	5.0mm
OSF	LAUFENN	5.0mm
OSR	LAUFENN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Front parking sensor
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Dented  
With Paint Damage



4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Dented  
With Paint Damage





9: Bumper Rear  
Scratched  
Over 100mm Thru Paint



10: Wheel osr  
Scratched  
Over 50mm



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Door osr  
Dented  
Over 30mm



13: Door osf  
Dented  
Over 30mm



14: Wing osf  
Dented  
Between 10mm + 30mm



15: Wheel osf  
Scratched  
Over 50mm



16: A Post os  
Chipped  
1 To 5



17: Roof  
Chipped  
Edge Chip

**Interior**

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**                      Average  
**Odour**                                      No

**Vehicle Inspection Report**

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK